## General Environmental Incident Summary

Incident: 3339 Date/Time Notice: 6/6/2014 1230 DEM Incident No:

Responsible Party: Pilot Logistics Services

Date Incident: 6/6/2014 Time Incident: 0130 Duration: 5 minutes

County: Mountrail Twp: 155 Rng: 94 Sec: 20 Qtr: Lat: 48.22741 Long: -102.79700 Method: Navigation quality GPS

Location Description: Drill pad location En Johnson 155-948017 located 8 miles south of Hwy 2 on

the left 0.5 mile down unnamed access road.

Submitted By: Max Burmeister Affiliation:

Address: 9874 Main Street

City: Woodsotock State: GA Zip: 30188

Received By:

Contact Person: Joey Cupp

5508 Lonas Drive Knoxville, TN 37909

Distance Nearest Occupied Building: Release Contained: No

Type of Incident: Hose connection failed during fuel transfer

Description of Released Contaminant: Red dye diesel.

Volume Spilled: 15.00 gallons Ag Related: No

EPA Extremely Hazardous Substance: Unknown Reported to NRC: Unknown

Cause of Incident:

A hose connection failed during a fuel transfer. 15 gallons of red dye diesel was spill on the ground surface measuring and area of 15 x 10 feet and approximately 8 inched in depth.

Risk Evaluation:

None

# of Fatalities: 0 # of Injuries: 0 Affected Medium: 03 - soil

Potential Environmental Impacts:

None following removal and replacement of impacted soil.

Action Taken or Planned:

Environmental restoration crew dispatched to perform excavation activities.

Wastes Disposal Location: Prairie View Lanfill

Agencies Involved:

## **Updates**

Date: 6/6/2014 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

## **Updated Volume:**

## Notes:

15-gallon diesel spill on the En Johnson 155-948017 well pad. NDIC retains oversight. Spill report forwarded to Cody Vanderbusch.